February 4, 1980

. 5

Mr. Roy E. Schrameck
State of Michigan
Department of Natural Resources
Pte. Mouilles State Game Preserve
Route #2
Rockwood, Michigan 48173

RE: Cancellation of All Waste Water Discharge Permits

Dear Mr. Schrameck:

On January 31, 1980, Ms. Catherine S. Morse & Chuck Bikfalvy of the DMR staff visited the Hi-Hill plant to inspect the zero discharge concept that is presently in existence. A couple of items were discovered that will be considered to be part of the process discharge.

Among these are the drains that the water test tanks are directed to when they are being emptied. The other items were the drains in the oil-acid storage room. The two attached drawings help clarify the items we are referring to.

A water re-cycle system is planned for the test tank area. The test water waste will be drained into a sump, pumped through a filter into a pH adjustment tank and then re-cycled back to the test tank.

We expect to have the system completed in eight weeks or less. At that point, we would consider the plant truly "Zero Discharge" and would expect that our discharge permits be cancelled.

Very truly yours, HI-MILL MANUFACTURING COMPANY

Robert F. Beard, President


Enclosures

cc: Ms. C. S. Morse

Mr. C. Bikfalvy

Mr. B. Zane

HI-MILL MH CO.



OMNI ENGINEERING


ACID-OIL STORAGE AREA


Showing the sealed drains

1. MAIN FLOOR DRAIN

2. DRAIN HOLE IN OIL

storage spill encasement
area.





SULFURIC KEEP LAGO ACID Ph Indicated IN EXISTING PRODUCT NEW PRESSURE PUMP EXISTIMS Tank FLOOR TEST DRAIN TANK FXIIING FILTER THE SUMP USE TRE-FORMED CONCRESE PIPE 36" DIA ¥ 4' RE-CYCLED TEST WATER

14444 11 11 11

NEW PARTS REQUIRED

- 1. SUMP TILE 36" I.D. X4"
- 2 PUMP & MOTOR 30 GPM 100 FT WATER
 MOTOR 440 V 1720 RPM MATCHED PI
- 3 FIVE GATE VALVES
- 4 ONE STEEL TANK (150 GAL.)
- 5. TWO INCH I.D. PLASTIC PIPE
- 6. PH INDICATOR CONTROLLER

OMNJ ENGINEERING HI MILL MFg. 20 Recycle Water System Test Room 2/3/8